

eK Core Mounting Instructions

Tools needed :

· Screw driver

 $\cdot \mbox{ eK}$ Core mounting package

- Instructions :
- 1. Print out the mounting template at 100 % size.
- 2. Tape the mounting template to the desired mounting surface, align the 4 big screws to the screw holes (\oplus) , and fasten the mounting plate to the surface.
- 3. Use the 3 small screws to secure the mounting bracket to the back of the eK Core.
- 4. Hang the eK Core to the mounting plate.

